

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AN207
SSW
1/4-1/2
0.332 mi.
1755 ft.
MANHOLE 42408
STILLWELL AVE & SURF AVE
BROOKLYN, NY
Site 5 of 6 in cluster AN

NY Spills S104651616
N/A

Relative:
Higher

Actual:
6 ft.

SPILLS:

Name: MANHOLE 42408
Address: STILLWELL AVE & SURF AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0000244 / 2002-01-17
Facility ID: 0000244
Facility Type: ER
DER Facility ID: 215967
Site ID: 265045
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2000-04-06
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-04-06
CID: 205
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-04-06
Spill Record Last Update: 2002-01-23
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #130778 Notes: 4-6-00 1 pint unknown oil on 1000gal water in manhole 42408. Manhole filled with water appears to be a tidal hole. Cannot tell if oil is contained. Sample taken. 4-6-00 0220hrs LSN 00-03356 <1ppm PCB 4-8-00 1500hrs Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump."

Remarks: "caller reports 1pt spill to 1,000 gallons water. con ed #130778"

All Materials:

Site ID: 265045
Operable Unit ID: 821981
Operable Unit: 01
Material ID: 288500
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported